

| SMA | | Location | | Access | | | | BMP Status | | | | | | | | | Sampler Status | | | | | | | | |
|----------------------|---------------|----------|--------|----------|------|------|----------------|------------|----------|----------------|---------|---------------------|--------------|--|--|-----------|----------------|---------|---------|--|-----------|-----------------|-------------------|---|--|
| Watershed | SMA | Mesa Top | Canyon | Pavement | Dirt | Foot | SMA Accessible | Baseline | Enhanced | Good Condition | Damaged | Routine Maintenance | Major Repair | Maintenance Notes | Cost: Minor-Green 0-5K, Moderate-Yellow 5-20K, Mod/Severe-Orange 20-50K, Severe-Red 50+K | Installed | Good Condition | Damaged | Missing | Recovered: (1) Cover (2) Body (3) Bottom | Serial | Battery missing | Battery Recovered | Notes | |
| Pajarito | 2M-SMA-1 | X | - | X | - | - | X | - | X | X | - | X | - | Repair 3 rock check dams | 3K | X | x | | | | 206M01502 | - | - | Equipment in good condition. No battery on-site. | |
| Pajarito | 2M-SMA-1.42 | X | - | X | - | - | X | - | X | X | - | X | - | Repair rock check dam | 2K | X | x | | | | 200E04215 | no | - | | |
| Pajarito | 2M-SMA-1.43 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | - | | | | | - | - | - | | |
| Pajarito | 2M-SMA-1.44 | X | - | X | - | - | X | - | X | X | - | - | - | - | - | X | x | - | - | - | 204G00160 | no | - | Turned off after collection. Reactivated 10/1/13. | |
| Pajarito | 2M-SMA-1.45 | X | - | X | - | - | X | - | X | X | - | - | - | - | - | X | x | | | | 207H00758 | no | - | Evidence of flow. | |
| Pajarito | 2M-SMA-1.5 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | X | X | - | - | - | 206K01538 | No | - | | |
| Pajarito | 2M-SMA-1.65 | X | - | - | X | - | X | - | X | X | - | - | - | - | - | X | X | | | | 198H01002 | No | Yes | Sampler turned off after collection and batter removed from field. | |
| Pajarito | 2M-SMA-1.67 | X | - | - | X | - | X | X | - | X | - | - | - | - | - | X | X | | | | 204G00156 | No | - | | |
| Pajarito | 2M-SMA-1.7 | X | - | X | - | - | X | - | X | X | - | - | - | - | - | X | X | - | - | - | 210F00999 | No | - | | |
| Pajarito | 2M-SMA-1.8 | X | - | X | - | - | X | - | X | X | - | - | X | Repair sealant | 20K | X | x | - | - | - | 198H01556 | - | - | Equipment in good condition. No battery on-site. | |
| Pajarito | 2M-SMA-1.9 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | - | | | | | - | - | - | | |
| Pajarito | 2M-SMA-2 | X | - | X | - | - | X | - | X | - | X | - | X | Repair backside of pond berm | 15K | X | | | | | 194J00434 | | | | |
| Pajarito | 2M-SMA-2.2 | X | - | X | - | - | X | - | X | X | - | - | X | Repair sealant | 20K | X | x | - | - | - | 198H01559 | - | - | Equipment in good condition. No battery on-site. | |
| Pajarito | 2M-SMA-2.5 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | - | | | | | - | - | - | | |
| Pajarito | 2M-SMA-3 | X | - | - | - | X | X | X | - | - | X | X | - | Replace 6 wattles | 3K | - | | | | | - | - | - | | |
| Pajarito | 3M-SMA-0.2 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | X | X | - | - | - | 204E01141 | No | - | | |
| Pajarito | 3M-SMA-0.4 | X | - | X | - | - | X | X | - | - | X | X | - | Repair berm | 5K | - | | | | | - | - | - | | |
| Pajarito | 3M-SMA-0.5 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | X | | X | | | 197G01959 | No | - | Sampler collected sediment. Needs to be cleaned and reactivated. | |
| Pajarito | 3M-SMA-0.6 | X | - | X | X | - | X | X | - | X | - | - | - | - | - | X | X | - | - | - | 202G04258 | No | - | | |
| Pajarito | 3M-SMA-2.6 | - | X | - | - | X | X | X | - | X | - | - | - | - | - | X | | | | | 209F01131 | | | | |
| Pajarito | 3M-SMA-4 | - | X | - | - | X | X | X | - | - | X | - | X | Repair gabions/riprap/channel | 50K | X | | X | X | | 208F01275 | Yes | | Sampler found downstream near PJ-SMA-14.3, taken to Pueblo Complex for repair. Actuator and tubing missing. | |
| Los Alamos/Pueblo | ACID-SMA-1.05 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | - | | | | | - | - | - | | |
| Los Alamos/Pueblo | ACID-SMA-2 | - | X | - | - | X | X | X | - | - | X | X | - | Clean out channel, repair berm | 20K | - | | | | | - | - | - | | |
| Los Alamos/Pueblo | ACID-SMA-2.01 | X | - | - | - | X | X | X | - | X | - | - | - | - | - | X | X | | | | 210F01626 | No | - | | |
| Los Alamos/Pueblo | ACID-SMA-2.1 | - | X | X | - | - | X | X | - | - | X | X | - | Same BMPs as ACID-2 | 20K | - | | | | | - | - | - | | |
| Ancho/Chaquehui | A-SMA-1.1 | - | X | X | - | - | X | X | - | X | - | - | - | - | - | X | X | | | | 209F01154 | No | - | | |
| Ancho/Chaquehui | A-SMA-2 | - | X | X | - | - | X | X | - | - | X | X | - | Repair/replace 11 wattles | 5K | X | X | | | | 210F01628 | No | - | Turned off after collection. | |
| Ancho/Chaquehui | A-SMA-2.5 | - | X | X | - | - | X | X | - | X | - | - | - | - | - | X | X | | | | 194J00432 | No | - | | |
| Ancho/Chaquehui | A-SMA-2.7 | - | X | X | - | - | X | - | X | X | - | X | - | Rake rills & mulch around berms 15 & 16 | 3K | X | X | | | | 194J00430 | No | - | Turned off after collection. | |
| Ancho/Chaquehui | A-SMA-2.8 | - | X | X | - | - | X | X | - | X | - | - | - | - | - | X | X | - | - | - | 204G00145 | No | - | | |
| Ancho/Chaquehui | A-SMA-3 | - | X | X | - | - | X | X | - | - | X | - | X | Replace 9 rock check dams | 10K | X | | | | | 209F01930 | | | | |
| Ancho/Chaquehui | A-SMA-3.5 | - | X | X | - | - | X | X | - | X | - | - | - | - | - | - | | | | | - | - | - | | |
| Ancho/Chaquehui | A-SMA-4 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | X | X | | | | 209F01128 | No | - | | |
| Ancho/Chaquehui | A-SMA-6 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | - | | | | | - | - | - | | |
| Los Alamos/Pueblo | B-SMA-0.5 | - | X | - | X | - | X | X | - | X | - | X | - | Add rock to check dam; repair 1 berm breach | 8K | X | | X | | | 198H01554 | No | - | Turned off after collection repair actuator and bonnet. | |
| Los Alamos/Pueblo | B-SMA-1 | - | X | - | - | X | X | X | - | X | - | X | - | Repair rock check dam | 5K | X | X | | | | 194J00436 | No | - | Turned off after collection. | |
| Sandia/Mortandad | CDB-SMA-0.15 | X | - | X | - | - | X | X | - | X | - | X | - | SMA rilling/gullies | 5K | X | X | - | - | - | 210F02112 | No | - | Insufficient volume collected, not retrieved | |
| Sandia/Mortandad | CDB-SMA-0.25 | - | X | - | X | - | X | - | X | - | X | - | X | Repair 3 berms | 22K | X | | | | | 210E01243 | | | | |
| Sandia/Mortandad | CDB-SMA-0.55 | - | X | - | X | - | X | X | - | X | - | - | - | - | - | X | X | | | | 210F00992 | No | Yes | Sampler turned off after collection and battery removed from field. Reactivated 9/30/13. | |
| Sandia/Mortandad | CDB-SMA-1 | X | - | X | - | - | X | - | X | X | - | X | - | Add rock for riprap | 5K | X | X | | | | 194J00416 | No | Yes | Sampler turned off after collection and battery removed from field. Reactivated 9/30/13. | |
| Sandia/Mortandad | CDB-SMA-1.15 | - | X | - | X | - | X | X | - | X | - | - | - | - | - | X | X | | | | 209F01148 | No | - | | |
| Sandia/Mortandad | CDB-SMA-1.35 | - | X | - | X | - | X | X | - | X | - | - | - | - | - | X | X | | | | 210E01716 | No | - | | |
| Sandia/Mortandad | CDB-SMA-1.54 | - | X | - | X | - | X | X | - | X | - | - | - | - | - | X | X | | | | 199J00371 | No | - | | |
| Sandia/Mortandad | CDB-SMA-1.55 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | X | X | | | | 209F01126 | No | - | | |
| Sandia/Mortandad | CDB-SMA-1.65 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | X | X | | | | 209F00292 | No | - | | |
| Sandia/Mortandad | CDB-SMA-4 | - | X | - | X | - | X | X | - | X | - | - | - | - | - | - | | | | | - | - | - | | |
| Water/Cañon de Valle | CDV-SMA-1.2 | X | - | - | X | - | X | X | - | X | - | X | - | Breach of 1 berm | 5K | X | X | | | | 204C00253 | No | - | Turned off after collection. | |
| Water/Cañon de Valle | CDV-SMA-1.3 | X | - | - | X | - | X | X | - | X | - | - | - | - | - | X | X | | | | 207C02027 | No | - | Turned off after collection. | |
| Water/Cañon de Valle | CDV-SMA-1.4 | X | - | - | X | - | X | - | X | X | - | X | - | Increased in erosion potential | 3K | X | x | - | - | - | 204C00260 | no | - | | |
| Water/Cañon de Valle | CDV-SMA-1.45 | X | - | - | X | - | X | - | X | X | - | - | - | - | - | X | | | | | 200E04210 | | | | |
| Water/Cañon de Valle | CDV-SMA-1.7 | X | X | - | - | X | X | X | - | X | - | - | - | - | - | X | X | | | | 200D00367 | No | - | Turned off after collection. | |
| Water/Cañon de Valle | CDV-SMA-2 | X | - | - | - | X | X | X | - | X | - | - | - | - | - | X | | | | | 205A00410 | | | | |
| Water/Cañon de Valle | CDV-SMA-2.3 | - | X | - | X | - | X | X | - | - | X | X | - | Replace rock check dams and | 5K | X | | | | | 207H00782 | | | | |
| Water/Cañon de Valle | CDV-SMA-2.41 | - | X | X | - | - | X | - | X | - | X | - | X | 3 berm breaches, rebuild channel, replace rock check dam | 35K | X | x | - | - | - | 200E04208 | no | - | | |
| Water/Cañon de Valle | CDV-SMA-2.42 | X | - | - | X | - | X | X | - | - | X | - | X | 1 large berm breach | 8K | X | | | | | 210F02106 | | | | |
| Water/Cañon de Valle | CDV-SMA-2.5 | X | - | - | X | - | X | X | - | - | X | - | X | Replace 2 wattles/7 rock check dams blown out or filled with sedimented/1 earth berm blown out | 15K | X | x | - | - | - | 210F02113 | no | yes | Sampler and battery removed from field 9/26/13. | |
| Water/Cañon de Valle | CDV-SMA-2.51 | X | - | X | - | - | X | X | - | - | X | X | - | Repair 2 rock check dams | 4K | X | X | | | | 209F01936 | No | - | Turned off after collection. | |
| Water/Cañon de Valle | CDV-SMA-3 | X | - | - | X | - | X | - | X | X | - | - | - | - | - | X | X | | | | 205A00403 | No | - | | |
| Water/Cañon de Valle | CDV-SMA-4 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | X | X | | | | 202G04289 | No | - | Moved screen and actuator 2 ft downstream to low point. | |
| Water/Cañon de Valle | CDV-SMA-6.01 | X | - | X | - | - | X | X | - | - | X | - | X | Replace wattle; repair earth berm and base course berm | 15K | X | X | | | | 209F00291 | No | - | Move screen and clean. | |
| Water/Cañon de Valle | CDV-SMA-6.02 | X | - | - | X | - | X | - | X | - | X | - | X | Runoff berm breach | 8K | X | X | | | | 203M01609 | No | - | Turned off after collection. Reactivated 9/30/13. | |
| Water/Cañon de Valle | CDV-SMA-7 | X | - | X | - | X | X | X | - | - | X | X | - | Repair runoff berm | 8K | X | X | | | | 207C01429 | No | - | Turned off after sample collection. | |

| SMA | | Location | | Access | | | | BMP Status | | | | | | | | Sampler Status | | | | | | | | | |
|----------------------|--------------|----------|--------|----------|------|------|----------------|------------|----------|----------------|---------|---------------------|--------------|---|--|----------------|----------------|---------|---------|--|-----------|-----------------|-------------------|--|--|
| Watershed | SMA | Mesa Top | Canyon | Pavement | Dirt | Foot | SMA Accessible | Baseline | Enhanced | Good Condition | Damaged | Routine Maintenance | Major Repair | Maintenance Notes | Cost: Minor-Green 0-5K, Moderate-Yellow 5-20K, Mod/Severe-Orange 20-50K, Severe-Red 50+K | Installed | Good Condition | Damaged | Missing | Recovered: (1) Cover (2) Body (3) Bottom | Serial | Battery missing | Battery Recovered | Notes | |
| Water/Cañon de Valle | CDV-SMA-8 | X | - | X | - | - | X | X | - | - | X | - | X | 3 rock check dams and 2 berms breached. New flow path forming from downed tree. | 18K | X | | | | | 207H00772 | | | | |
| Water/Cañon de Valle | CDV-SMA-8.5 | X | - | X | - | X | X | X | - | X | - | - | - | - | - | X | X | | | | 207H00898 | No | - | | |
| Water/Cañon de Valle | CDV-SMA-9.05 | X | - | - | - | | X | X | - | - | X | - | X | 3 berm breaches | 15K | X | X | | | | 210F01635 | No | - | | |
| Ancho/Chaquehui | CHQ-SMA-0.5 | X | - | - | - | X | X | X | - | X | - | - | - | - | - | X | x | - | - | - | 200D00365 | No | - | | |
| Ancho/Chaquehui | CHQ-SMA-1.01 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | X | X | - | - | - | 209F01146 | No | - | | |
| Ancho/Chaquehui | CHQ-SMA-1.02 | X | - | X | - | - | X | - | X | X | - | - | - | - | - | X | X | | | | 206J00409 | No | - | Turned off after collection. | |
| Ancho/Chaquehui | CHQ-SMA-1.03 | X | - | X | - | - | X | X | - | X | - | X | - | Repair rock check dam | 2K | - | | | | | - | - | - | | |
| Ancho/Chaquehui | CHQ-SMA-2 | - | X | X | - | - | X | X | - | X | - | - | - | - | - | - | | | | | - | - | - | | |
| Ancho/Chaquehui | CHQ-SMA-3.05 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | X | X | | | | 204G00155 | No | - | Turned off after collection. | |
| Ancho/Chaquehui | CHQ-SMA-4 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | X | X | | | | 198H01555 | No | - | | |
| Ancho/Chaquehui | CHQ-SMA-4.1 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | X | X | | | | 210F02108 | No | - | Turned off after collection. | |
| Ancho/Chaquehui | CHQ-SMA-4.5 | X | - | X | - | - | X | X | - | X | - | X | - | Repair rock check dam and | 4K | - | | | | | - | - | - | | |
| Ancho/Chaquehui | CHQ-SMA-5.05 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | X | X | - | - | - | 209F01149 | No | - | | |
| Ancho/Chaquehui | CHQ-SMA-6 | X | - | X | - | - | X | X | - | X | - | X | - | Replace 2 rock check dams | 3K | - | | | | | - | - | - | | |
| Ancho/Chaquehui | CHQ-SMA-7.1 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | X | X | - | - | - | 201F04069 | No | - | | |
| Los Alamos/Pueblo | DP-SMA-0.3 | X | X | X | - | - | X | - | X | X | - | - | - | - | - | X | x | | | | 207H00745 | no | Yes | Turned off after sample collection. Battery removed from field | |
| Los Alamos/Pueblo | DP-SMA-0.4 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | X | x | | | | 198H01010 | No | Yes | Turned off after sample collection. Battery removed from field | |
| Los Alamos/Pueblo | DP-SMA-0.6 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | X | x | | | | 207H00759 | no | - | | |
| Los Alamos/Pueblo | DP-SMA-1 | - | X | - | X | - | X | X | - | X | - | - | - | - | - | X | x | | | | 204C00248 | No | - | Sample missed no liquid detected | |
| Los Alamos/Pueblo | DP-SMA-2 | - | X | - | X | - | X | X | - | X | - | - | - | - | - | X | x | | | | 207F00601 | no | - | | |
| Los Alamos/Pueblo | DP-SMA-2.35 | X | - | - | X | - | X | X | - | X | - | - | - | - | - | X | x | - | - | - | 205A00407 | No | Yes | Turned off after sample collection. Battery removed from field | |
| Los Alamos/Pueblo | DP-SMA-3 | X | - | X | - | - | X | - | X | X | - | X | - | Hand repair berm, possibly move spillway | 5K | X | X | - | - | - | 200D02413 | No | - | | |
| Los Alamos/Pueblo | DP-SMA-4 | X | - | - | X | - | X | X | - | X | - | X | - | Repair rock check dam | 3K | X | X | - | - | - | 207H00781 | No | - | | |
| Water/Cañon de Valle | F-SMA-2 | X | X | - | X | - | X | - | X | - | X | - | X | 4 berms breached | 16K | X | x | - | - | - | 209F01934 | No | - | | |
| Los Alamos/Pueblo | LA-SMA-0.85 | X | - | X | - | - | X | - | X | X | - | - | - | - | - | X | x | - | - | - | 200D02383 | No | Yes | Sampler and battery removed from field 9/26/13 | |
| Los Alamos/Pueblo | LA-SMA-0.9 | X | X | X | - | - | X | X | - | - | X | - | X | 6 berm modifications | 10K | X | X | - | - | - | 210F01636 | No | - | | |
| Los Alamos/Pueblo | LA-SMA-1 | X | X | X | - | - | X | - | X | - | X | - | X | Flood assessment indicated | 10K | X | X | | | | 210F01633 | | | Reactivated 9/30/13 | |
| Los Alamos/Pueblo | LA-SMA-1.1 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | - | | | | | - | - | - | | |
| Los Alamos/Pueblo | LA-SMA-1.25 | X | X | X | - | - | X | - | X | - | X | X | - | Repair base course berm (only run-on control) | 8K | - | | | | | - | - | - | | |
| Los Alamos/Pueblo | LA-SMA-10.11 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | X | X | | | | 207H00768 | No | - | | |
| Los Alamos/Pueblo | LA-SMA-10.12 | X | - | X | - | - | X | - | X | X | - | - | - | - | - | X | X | | | | 204C00267 | No | Yes | Turned off after sample collection. Battery removed from field. Reactivated 9/30/13. | |
| Los Alamos/Pueblo | LA-SMA-2.1 | X | - | - | - | X | X | X | - | - | X | - | X | Repair log berm and replace riprap | 8K | X | X | - | - | - | 198H01022 | no | Yes | Turned off after sample collection. Battery removed from field. | |
| Los Alamos/Pueblo | LA-SMA-2.3 | X | - | - | - | X | X | X | - | X | - | - | - | - | - | X | | | | | 200G01116 | | | | |
| Los Alamos/Pueblo | LA-SMA-3.1 | X | - | - | - | X | X | X | - | X | - | - | - | - | - | X | | | | | 207C01435 | | | | |
| Los Alamos/Pueblo | LA-SMA-3.9 | X | - | - | - | X | X | X | - | X | - | - | - | - | - | X | | | | | 209F00285 | | | | |
| Los Alamos/Pueblo | LA-SMA-4.1 | X | - | - | - | X | X | X | - | X | - | X | - | Repair rock check dam | 3K | - | | | | | - | - | - | | |
| Los Alamos/Pueblo | LA-SMA-4.2 | X | - | - | - | X | X | X | - | - | X | X | - | Hand repair 3 water bars | 3K | X | | | | | 200D00379 | | | | |
| Los Alamos/Pueblo | LA-SMA-5.01 | X | - | - | - | X | X | X | - | - | X | X? | - | Hand repair rock berm and 2 water bars; replace wattle | 8K | X | | | | | 203B01843 | | | | |
| Los Alamos/Pueblo | LA-SMA-5.02 | X | - | - | - | X | X | X | - | - | X | X | - | Replace 3 wattles (only runoff controls) | 2K | X | | | | | 204M00458 | | | | |
| Los Alamos/Pueblo | LA-SMA-5.2 | X | X | X | - | - | X | X | - | - | X | X | - | Modify log berms (only runoff controls) | 6K | X | | | | | 202G04285 | | | | |
| Los Alamos/Pueblo | LA-SMA-5.31 | - | X | X | - | - | X | - | X | X | - | X | - | Repair 2 rock berms | 5K | X | | | | | 204F00147 | | | | |
| Los Alamos/Pueblo | LA-SMA-5.33 | X | - | - | - | X | X | - | X | X | - | - | - | - | - | - | | | | | - | - | - | | |
| Los Alamos/Pueblo | LA-SMA-5.35 | X | - | X | - | - | X | - | X | X | - | - | - | - | - | X | | | | | 209F00718 | | | | |
| Los Alamos/Pueblo | LA-SMA-5.361 | X | - | - | - | X | X | X | - | X | - | - | - | - | - | X | x | | | | 209F01142 | no | - | | |
| Los Alamos/Pueblo | LA-SMA-5.362 | X | - | - | - | X | X | X | - | X | - | - | - | - | - | X | x | | | | 204G00159 | no | - | | |
| Los Alamos/Pueblo | LA-SMA-5.51 | X | - | X | - | - | X | X | - | - | X | - | X | 2 berm breaches | 6K | X | | | | | 201F04080 | | | | |
| Los Alamos/Pueblo | LA-SMA-5.52 | X | - | X | - | - | X | X | - | - | X | - | X | Repair berm; modify rock check | 8K | X | X | | | | 202G03258 | No | - | | |
| Los Alamos/Pueblo | LA-SMA-5.53 | X | - | X | - | - | X | X | - | X | - | X | - | Replace 2 wattles | 2K | X | | | | | 206B00099 | | | | |
| Los Alamos/Pueblo | LA-SMA-5.54 | X | - | X | - | - | X | X | - | - | X | X | - | Replace 2 wattles | 2K | X | | | | | 207H00776 | | | | |
| Los Alamos/Pueblo | LA-SMA-5.91 | X | - | - | - | X | X | - | X | - | X | X | - | Repair log check dams (only runoff control) | 8K | X | X | - | - | - | 198H01005 | No | Yes | Turned off after sample collection. Battery removed from field. | |
| Los Alamos/Pueblo | LA-SMA-5.92 | X | - | - | - | X | X | X | - | - | X | - | X | Repair 2 berms | 10K | X | X | - | - | - | 204C00262 | No | Yes | Sampler and battery removed from field 9/26/13. | |
| Los Alamos/Pueblo | LA-SMA-6.25 | X | X | X | X | - | X | X | - | - | X | X | - | Replace wattles (only runoff | 2K | X | | | | | 198H01015 | | | | |
| Los Alamos/Pueblo | LA-SMA-6.27 | X | X | X | X | - | X | X | - | - | X | X | - | Replace wattles (only runoff | 2K | X | x | - | - | - | 209F00286 | No | - | | |
| Los Alamos/Pueblo | LA-SMA-6.3 | X | X | X | X | - | X | X | - | X | - | X | - | Repair rock check dam | 3K | X | X | | | | 200E04223 | No | - | Cleaned debris from around actuator. | |
| Los Alamos/Pueblo | LA-SMA-6.31 | X | X | X | X | - | X | X | - | - | X | X | - | Replace wattles (only runoff | 3K | X | X | | | | 207B00205 | No | - | Dug actuator out, buried in ~ 2 ft of pumice sand. | |
| Los Alamos/Pueblo | LA-SMA-6.32 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | X | X | - | - | - | 208F01272 | No | - | | |
| Los Alamos/Pueblo | LA-SMA-6.34 | X | X | X | X | - | X | X | - | X | - | - | - | - | - | X | X | | | | 207H00762 | No | - | | |
| Los Alamos/Pueblo | LA-SMA-6.36 | X | X | X | X | - | X | X | - | X | - | - | - | - | - | X | X | | | | 207H00767 | No | - | | |
| Los Alamos/Pueblo | LA-SMA-6.38 | X | X | X | X | - | X | X | - | X | - | - | - | - | - | X | X | | | | 207H00892 | No | - | | |
| Los Alamos/Pueblo | LA-SMA-6.395 | X | X | X | X | - | X | | | | | | | | | | | | | | | | | | |

| SMA | | Location | | Access | | | | BMP Status | | | | | | | | Sampler Status | | | | | | | | | |
|----------------------|----------------|----------|--------|----------|------|------|----------------|------------|----------|----------------|---------|---------------------|--------------|---|--|----------------|----------------|---------|---------|--|-----------|-----------------|-------------------|--|--|
| Watershed | SMA | Mesa Top | Canyon | Pavement | Dirt | Foot | SMA Accessible | Baseline | Enhanced | Good Condition | Damaged | Routine Maintenance | Major Repair | Maintenance Notes | Cost: Minor-Green 0-5K, Moderate-Yellow 5-20K, Mod/Severe-Orange 20-50K, Severe-Red 50+K | Installed | Good Condition | Damaged | Missing | Recovered: (1) Cover (2) Body (3) Bottom | Serial | Battery missing | Battery Recovered | Notes | |
| Sandia/Mortandad | M-SMA-1.22 | X | - | - | X | - | X | - | X | X | - | - | - | - | - | X | X | | | | 198H01011 | No | - | turned off after collection. Reactivated 9/30/13 | |
| Sandia/Mortandad | M-SMA-10 | X | X | - | X | - | X | X | - | X | - | - | - | - | - | - | - | | | | - | - | - | | |
| Sandia/Mortandad | M-SMA-10.01 | X | X | - | X | - | X | - | X | X | - | - | - | - | - | X | X | - | - | - | 200D02398 | No | - | | |
| Sandia/Mortandad | M-SMA-10.3 | X | X | - | X | - | X | X | - | X | - | X | - | Add gravel bags around drop | 2K | - | | | | | - | - | - | | |
| Sandia/Mortandad | M-SMA-11.1 | X | X | - | X | - | X | X | - | X | - | - | - | - | - | X | X | | | | 207H01447 | No | - | | |
| Sandia/Mortandad | M-SMA-12 | X | X | - | X | X | X | X | - | X | - | - | - | - | - | X | | x | | | 207C02028 | No | - | Sampler found on its side after 9/23 event. Battery cable cut. Reset at inspection | |
| Sandia/Mortandad | M-SMA-12.5 | X | - | - | X | - | X | X | - | X | - | - | - | - | - | X | X | - | - | - | 209F01150 | No | - | | |
| Sandia/Mortandad | M-SMA-12.6 | X | - | - | X | - | X | X | - | - | X | X | - | Repair breach in berm (hand work) | 3K | X | X | | | | 209F01141 | No | - | Turned off after collection. | |
| Sandia/Mortandad | M-SMA-12.7 | X | - | - | X | - | X | X | - | X | - | - | - | - | - | X | X | - | - | - | 200D00382 | No | - | | |
| Sandia/Mortandad | M-SMA-12.8 | X | - | - | X | - | X | X | - | X | - | - | - | - | - | X | X | - | - | - | 209F00288 | No | - | | |
| Sandia/Mortandad | M-SMA-12.9 | X | - | - | X | - | X | X | - | X | - | - | - | - | - | X | X | - | - | - | 209E01529 | No | - | | |
| Sandia/Mortandad | M-SMA-12.92 | - | X | - | X | - | X | X | - | - | X | - | X | Mortandad sediemt traps. Also refer to Attachament ??. | 100+K | X | | X | | | 209F01122 | No | - | Power failed. Battery was washed yards away. Two pin connector broke, sampler turned on side by flowing water. Moved sampler intake out of flume. Flume blocked by debris. Two pin replaced and battery reattached at inspection, no further maintenance. recommended. | |
| Sandia/Mortandad | M-SMA-13 | X | - | - | X | - | X | X | - | X | - | - | - | - | - | X | X | | | | 210F00994 | No | - | Turned off after collection. | |
| Sandia/Mortandad | M-SMA-3 | X | - | X | - | - | X | X | - | X | - | X | - | Riprap extension | 5K | - | | | | | - | - | - | | |
| Sandia/Mortandad | M-SMA-3.1 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | X | X | - | - | - | 200D00388 | No | - | | |
| Sandia/Mortandad | M-SMA-3.5 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | X | X | - | - | - | 210E01705 | No | - | | |
| Sandia/Mortandad | M-SMA-4 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | X | x | | x | | 210F01623 | - | - | ISCO in good condition. Actuator missing. No battery on-site. | |
| Sandia/Mortandad | M-SMA-5 | X | X | X | - | - | X | X | - | X | - | - | - | - | - | X | X | - | - | - | 198H00993 | No | - | | |
| Sandia/Mortandad | M-SMA-6 | X | X | X | X | - | X | X | - | - | X | X | - | Modify 3 rock check dams; add rock to riprap; modify gravel bag | 12K | - | | | | | - | - | - | | |
| Sandia/Mortandad | M-SMA-7 | X | X | - | X | - | X | X | - | X | - | - | - | - | - | - | | | | | - | - | - | | |
| Sandia/Mortandad | M-SMA-7.9 | X | X | X | X | | X | X | - | - | X | - | X | 2 berm breaches | 10K | X | X | | | | 204B00769 | No | Yes | Turned off after sample collection. Battery removed from field. | |
| Sandia/Mortandad | M-SMA-9.1 | X | X | X | X | - | X | X | - | X | - | - | - | - | - | X | X | - | - | - | 210F00998 | No | - | | |
| Pajarito | PJ-SMA-1.05 | X | - | - | X | X | X | X | - | - | X | X | - | 1 berm breach | 4K | X | x | - | - | - | 210E01707 | no | - | Sampler off. Several power and failure messages. Turned off after sample collection. | |
| Pajarito | PJ-SMA-10 | X | - | - | X | | X | X | - | X | - | - | - | - | - | X | X | | | | 201E02744 | No | - | Moved upstream 1 ft. | |
| Pajarito | PJ-SMA-11 | X | - | - | X | - | X | X | - | - | X | | X | - | - | X | | | | | 204A01823 | | | | |
| Pajarito | PJ-SMA-11.1 | X | - | - | X | - | X | X | - | - | X | - | X | 3 new berms | 10K | X | | | | | 204C00261 | | | | |
| Pajarito | PJ-SMA-13 | - | X | X | - | - | X | X | - | X | - | - | - | - | - | X | X | | | | 209F01140 | No | - | | |
| Pajarito | PJ-SMA-13.7 | - | X | X | - | - | X | - | X | X | - | - | - | - | - | X | X | | | | 204M00353 | No | - | | |
| Pajarito | PJ-SMA-14 | X | | X | - | - | X | X | - | X | - | X | - | Rake rills & mulch | 3K | X | X | | | | 206M01493 | No | - | | |
| Pajarito | PJ-SMA-14.2 | - | X | X | - | - | X | X | - | - | X | X | - | Replace rock check dams | 3K | X | | X | | | 200G01115 | No | - | Actuator and tubing deeply buried beneath mud. | |
| Pajarito | PJ-SMA-14.3 | - | X | X | - | - | X | X | - | - | X | X | - | Install new wattle | 2K | X | | | X | | 207A01861 | Yes | | Sampler is missing. Tubing and clamp are only items at location | |
| Pajarito | PJ-SMA-14.4 | - | X | X | - | - | X | X | - | X | - | - | - | - | - | X | X | | | | 209F00293 | No | - | | |
| Pajarito | PJ-SMA-14.6 | - | X | X | - | - | X | X | - | X | - | - | - | - | - | X | X | | | | 204C00252 | No | - | | |
| Pajarito | PJ-SMA-14.8 | - | X | X | - | - | X | X | - | X | - | X | - | Install new wattle | 2K | - | | | | | - | - | - | | |
| Pajarito | PJ-SMA-16 | - | X | X | - | - | X | X | - | X | - | - | - | - | - | - | | | | | - | - | - | | |
| Pajarito | PJ-SMA-17 | X | X | X | - | X | X | X | - | X | - | X | - | Repair TA-54 facility? | 8K | - | | | | | - | - | - | | |
| Pajarito | PJ-SMA-18 | X | - | - | X | - | X | X | - | X | - | X | - | Repair TA-54 facility? | 8K | - | | | | | - | - | - | | |
| Pajarito | PJ-SMA-19 | X | - | - | X | - | X | X | - | X | - | X | - | Replace rock check dam | 5K | - | | | | | - | - | - | | |
| Pajarito | PJ-SMA-2 | X | - | - | X | - | X | X | - | X | - | X | - | Replace 3 rock check dams | 3K | X | X | - | - | - | 209F01155 | No | - | | |
| Pajarito | PJ-SMA-20 | X | - | - | X | - | X | X | - | X | - | - | - | - | - | - | | | | | - | - | - | | |
| Pajarito | PJ-SMA-3.05 | X | - | - | X | - | X | - | X | X | - | - | - | - | - | X | X | - | - | - | 209F01115 | No | - | Evidence of slight flow. | |
| Pajarito | PJ-SMA-4.05 | X | - | X | - | - | X | X | - | - | X | - | X | Replace runon rock check dam/repair runoff berm breach | 10K | X | x | - | - | - | 209F01127 | No | Yes | Turned off after sample collection. Battery removed from field. | |
| Pajarito | PJ-SMA-5 | X | - | - | X | - | X | X | - | X | - | - | - | - | - | - | | | | | - | - | - | | |
| Pajarito | PJ-SMA-5.1 | X | - | - | X | - | X | - | X | X | - | - | - | - | - | X | x | | | | 204M00356 | no | - | Evidence of flow. Sample missed no liquid detected. | |
| Pajarito | PJ-SMA-6 | X | - | - | X | - | X | X | - | X | - | X | - | Repair rilling on 2 berms and add more seed/mulch | 7K | X | X | | | | 210F01631 | No | - | Clean and move screen and actuator. | |
| Pajarito | PJ-SMA-7 | X | - | X | - | - | X | X | - | - | X | - | X | Rebuild berm-update MSS maint WO | 10K | X | | | | | 210F01632 | | | | |
| Pajarito | PJ-SMA-8 | X | - | X | - | - | X | X | - | - | X | X | - | 1 berm/1 rock check dam | 10K | X | X | | | | 210E01717 | No | - | Move screen and actuator. | |
| Pajarito | PJ-SMA-9 | X | - | X | - | - | X | X | - | X | - | X | - | Repair 2 rock check dam | 3K | X | | X | | | 210F01641 | No | - | Partial sample oot retrieved. Sampler needs to be reactivated and cleaned out around screen. | |
| Sandia/Mortandad | PRATT-SMA-1.05 | - | X | | | | X | X | - | - | X | X | - | 1 berm/1 rock check dam | 15K | X | X | | | | 209F01123 | NO | Yes | Turned off after sample collection. Battery removed from field. | |
| Los Alamos/Pueblo | P-SMA-0.3 | - | X | - | X | - | X | X | - | - | X | - | X | Rebuild berm | 8K | X | X | - | - | - | 207G00426 | NO | Yes | Sampler and battery removed from field 9/20/13. Sample not retrieved, monitoring complete. | |
| Los Alamos/Pueblo | P-SMA-1 | - | X | - | X | - | X | X | - | - | X | - | X | Needs an engineer assessment | 75K | X | x | - | - | - | 204C00265 | No | - | | |
| Los Alamos/Pueblo | P-SMA-2 | - | X | - | X | X | X | X | - | - | X | X | - | Base course berm breach/rock berm build up (only runoff | 15K | X | X | | | | 200E03270 | No | - | Sampler turned over, but inhibited. Reset at inspection. | |
| Los Alamos/Pueblo | P-SMA-2.15 | - | X | - | X | X | X | X | - | X | - | X | - | Build up & extend rock check dam | 5K | X | x | | | | 198H00980 | no | - | | |
| Los Alamos/Pueblo | P-SMA-2.2 | X | X | - | - | X | X | X | - | X | - | - | - | - | - | X | X | - | - | - | 200E04209 | No | - | | |
| Los Alamos/Pueblo | P-SMA-3.05 | X | - | X | - | - | X | X | - | - | X | - | X | Repair 2 berm | 8K | X | X | - | - | - | 204F00141 | No | - | Sampler turned off after collection | |
| Water/Cañon de Valle | PT-SMA-0.5 | X | - | X | - | - | X | - | X | - | X | - | X | Berm breaches | 10K | X | X | | | | 204F00148 | No | - | Turned off after collection. Reactivated 9/30/13. | |
| Water/Cañon de Valle | PT-SMA-1 | X | - | X | - | - | X | - | X | X | - | - | - | - | - | X | X | - | - | - | 210E01706 | No | - | | |
| Water/Cañon de Valle | PT-SMA-1.7 | X | - | X | - | - | X | - | X | X | - | - | - | - | - | X | | | | | 209F01119 | | | | |
| Water/Cañon de Valle | PT-SMA-2 | X | - | X | - | - | X | X | - | X | - | X | - | 1 berm breach | 5K | X | X | - | - | - | 204F00150 | No | - | | |
| Water/Cañon de Valle | PT-SMA-2.01 | X | - | X | - | - | X | - | X | X | - | - | - | - | - | X | X | - | - | - | 200D02414 | No | - | | |
| Water/Cañon de Valle | PT-SMA-3 | - | X | X | - | - | X | X | - | - | X | - | X | Needs LANL field assessment | 20K | X | | X | | | 210F00996 | No | - | Need to reair actuator, remove debris. | |
| Water/Cañon de Valle | PT-SMA-4.2 | - | X | X | X | - | X | X | - | X | - | - | - | - | - | X | X | - | - | - | 202E02330 | No | - | Found tipped over at inspection. Conducted maintenance at visit. | |
| Los Alamos/Pueblo | R-SMA-0.5 | X | - | - | X | - | X | X | - | X | - | - | - | - | - | - | | | | | - | - | - | | |
| Los Alamos/Pueblo | R-SMA-1 | - | X | X | - | - | X | X | - | - | X | - | X | Repair gabion & channel | 40K | - | | | | | - | - | - | | |
| Los Alamos/Pueblo | R-SMA-1.95 | - | X | - | X | - | X | - | X | X | - | - | - | - | - | - | | | | | - | - | - | | |

| SMA | | Location | | Access | | | | BMP Status | | | | | | | | Sampler Status | | | | | | | | | |
|----------------------|---------------|----------|--------|----------|------|------|----------------|------------|----------|----------------|---------|---------------------|--------------|--|--|----------------|-----------------------|---------|---------|--|-----------|-----------------|---|---|--|
| Watershed | SMA | Mesa Top | Canyon | Pavement | Dirt | Foot | SMA Accessible | Baseline | Enhanced | Good Condition | Damaged | Routine Maintenance | Major Repair | Maintenance Notes | Cost: Minor-Green 0-5K, Moderate-Yellow 5-20K, Mod/Severe-Orange 20-50K, Severe-Red 50+K | Installed | Good Condition | Damaged | Missing | Recovered: (1) Cover (2) Body (3) Bottom | Serial | Battery missing | Battery Recovered | Notes | |
| Los Alamos/Pueblo | R-SMA-2.05 | - | X | - | - | X | X | X | - | X | - | - | - | - | - | X | X | - | - | - | 201F04062 | No | - | | |
| Los Alamos/Pueblo | R-SMA-2.3 | - | X | - | - | X | X | X | - | - | X | X | - | Replace juniper bale (only runoff control) | 4K | - | | | | | - | - | - | | |
| Los Alamos/Pueblo | R-SMA-2.5 | - | X | - | X | - | X | X | - | X | - | - | - | - | - | X | X | - | - | - | 200E04207 | No | - | | |
| | | | | | | | | | | | | | | | | | | | | | | | | | |
| Sandia/Mortandad | S-SMA-0.25 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | - | | | | | - | - | - | | |
| Sandia/Mortandad | S-SMA-1.1 | X | - | X | - | - | X | - | X | X | - | X | - | Repair major rills/gullies to sediment pond berm | 20K | X | X | | | | 207H00904 | No | - | | |
| Sandia/Mortandad | S-SMA-2 | X | - | X | - | - | X | - | X | X | - | - | - | - | - | X | x | - | - | - | 194J00400 | No | Yes | Sampler and battery removed from field 9/26/13. | |
| Sandia/Mortandad | S-SMA-2.01 | X | - | X | - | - | X | - | X | X | - | - | - | - | - | X | X | | | | 204G00164 | No | - | Turned off after collection. Reactivated 9/30/13. | |
| Sandia/Mortandad | S-SMA-2.8 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | X | X | | | | 205A00395 | No | - | | |
| Sandia/Mortandad | S-SMA-3.51 | X | - | X | - | - | X | X | - | X | - | X | - | Rebuild 2 rock check dams | 2K | X | X | | | | 198H01550 | No | - | | |
| Sandia/Mortandad | S-SMA-3.52 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | X | X | | | | 207H00780 | No | - | | |
| Sandia/Mortandad | S-SMA-3.53 | X | X | X | - | - | X | - | X | - | X | X? | - | Reshape channel/extend riprap | 15K | X | X | | | | 200D00375 | No | - | | |
| Sandia/Mortandad | S-SMA-3.6 | X | - | - | X | - | X | - | X | - | X | X | - | Ecoblock/extend riprap | 5K | - | | | | | - | - | - | | |
| Sandia/Mortandad | S-SMA-3.7 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | X | X | | | | 209F01145 | No | - | | |
| Sandia/Mortandad | S-SMA-3.71 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | X | X | - | - | - | 208F01276 | No | - | Reactivated 10/1/13. | |
| Sandia/Mortandad | S-SMA-3.72 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | X | X | - | - | - | 209F01929 | No | - | | |
| Sandia/Mortandad | S-SMA-3.95 | - | X | X | - | - | X | X | - | - | X | X | - | Replace wattles | 3K | X | | | | | 210E01704 | | | | |
| Sandia/Mortandad | S-SMA-4.1 | X | - | X | - | - | X | - | | - | X | X | - | Replace wattlesrepair /rock berm repair/seed and mulch | 12K | X | X | | | | 198B00454 | | | Reactivated 9/30/13. | |
| Sandia/Mortandad | S-SMA-4.5 | - | X | - | X | - | X | X | - | X | - | X | - | Replace wattles | 3K | X | | | | | 208F01274 | | | | |
| Sandia/Mortandad | S-SMA-5 | - | X | X | - | - | X | X | - | - | X | - | X? | Replace riprap & spillway/berm sedimented in | 15K | X | | | | | 210F01624 | | | | |
| Sandia/Mortandad | S-SMA-5.2 | - | X | X | - | - | X | X | - | X | - | X | - | Extend 2 rock check dams | 3K | X | x | - | - | - | 207A01863 | no | - | | |
| Sandia/Mortandad | S-SMA-5.5 | - | X | - | X | - | X | X | - | X | - | - | - | - | - | X | x | - | - | - | 210E01715 | no | - | | |
| Sandia/Mortandad | S-SMA-6 | - | X | X | | - | X | X | - | - | X | - | X | 2 coir logs washed away/3 rock check dams blown out | 30K | - | | | | | - | - | - | | |
| Pajarito | STRM-SMA-1.05 | X | - | X | | - | X | - | X | X | - | X | - | Repair riprap repair (only runoff control) | 5K | - | | | | | - | - | - | | |
| Pajarito | STRM-SMA-1.5 | X | - | - | X | - | X | - | X | - | X | - | X? | Remove needlecase, repair 3 spillways | 10K | X | X | | | | 207H00774 | No | Yes | Sampler turned off after collection and battery removed from field. Reactivated 9/30/13. | |
| Pajarito | STRM-SMA-4.2 | X | - | - | X | - | X | - | X | X | - | - | - | - | - | X | | | | | 209F01132 | | | | |
| Pajarito | STRM-SMA-5.05 | X | - | - | X | - | X | - | X | - | X | X | - | Repair berm breach/rilling | 10K | X | | | | | 210F01630 | | | | |
| Sandia/Mortandad | T-SMA-1 | X | - | - | X | - | X | - | X | X | - | X | - | Erosion above & between culverts | 18K | - | | | | | - | - | - | | |
| Sandia/Mortandad | T-SMA-2.5 | X | X | X | - | - | X | X | - | X | - | - | - | - | - | X | X | - | - | - | 208F01277 | No | - | | |
| Sandia/Mortandad | T-SMA-2.85 | X | X | X | - | - | X | X | - | X | - | - | - | - | - | - | | | | | - | - | - | | |
| Sandia/Mortandad | T-SMA-3 | X | X | - | X | - | X | X | - | X | - | X | - | Build up and extend 2 runoff log check dams | 15K | - | | | | | - | - | - | | |
| Sandia/Mortandad | T-SMA-4 | - | X | - | X | - | X | X | - | - | X | X | - | Repair log berm (only ROF controls for 1 Site) | 8K | X | X | | | | 206B00105 | No | Yes | Sampler turned off after collection and battery removed from field. Reactivated 9/30/13. | |
| Sandia/Mortandad | T-SMA-5 | - | X | - | X | - | X | X | - | X | - | X | - | Repair rock berm & check dam | 5K | X | X | | | | 205A00369 | No | - | | |
| Sandia/Mortandad | T-SMA-6.8 | - | X | - | X | - | X | X | - | - | X | X | - | Modify gravel bag (only runoff control) | 5K | X | | x | | | 210E01246 | No | - | Sample tubing was pulled out of sampler by downstream flow of stream. Evident by debris direction about sampler intake and rebar. Sample water not from outfall upslope. Cleaned intake and attach tubing for continued monitoring. | |
| Sandia/Mortandad | T-SMA-7 | - | X | - | X | - | X | X | - | X | - | - | - | - | - | X | x | | | | 207H00777 | NO | - | | |
| Sandia/Mortandad | T-SMA-7.1 | - | X | - | X | - | X | X | - | X | - | X | - | Repair base course berm | 8K | X | x | | | | 204B00750 | no | - | | |
| Water/Cañon de Valle | W-SMA-1 | X | - | X | - | - | X | - | X | - | X | - | X | Replace all riprap | 10K | X | x | - | - | - | 209F01120 | no | - | Turned off after collection. | |
| Water/Cañon de Valle | W-SMA-1.5 | X | - | X | - | - | X | - | X | X | - | - | - | - | - | X | | | | | 205A00424 | | | | |
| Water/Cañon de Valle | W-SMA-10 | X | - | X | - | - | X | - | X | X | - | X | - | Repair spillway | 12K | X | | x | | | 204C00243 | NO | - | Sample intake washed out. Replaced in approx place. Sample intake tube pulled from sample. Sample missed no liquid detected. Reset at inspection. | |
| Water/Cañon de Valle | W-SMA-11.7 | X | - | - | X | - | X | - | X | X | - | X | - | 1 berm breach | 5K | X | x | | | | 210F01629 | no | - | Turned off after collection. Reactivated 9/30/13. | |
| Water/Cañon de Valle | W-SMA-12.05 | X | - | - | X | - | X | X | | X | - | - | - | - | - | X | X | | | | 207H00906 | No | - | | |
| Water/Cañon de Valle | W-SMA-14.1 | X | - | X | - | - | X | - | X | | X | X | | - | - | X | Actuator needs repair | | | 194J00447 | No | - | Turned off after collection. Reactivated 9/30/13. | | |
| Water/Cañon de Valle | W-SMA-15.1 | X | - | X | - | - | X | - | X | X | - | - | - | - | - | X | | | | | 209H01282 | | | | |
| Water/Cañon de Valle | W-SMA-2.05 | X | - | X | - | - | X | - | X | X | - | - | - | - | - | X | | | | | 209F01133 | | | | |
| Water/Cañon de Valle | W-SMA-3.5 | X | - | - | X | - | X | X | - | X | - | - | - | - | - | X | | | | | 210E01714 | | | | |
| Water/Cañon de Valle | W-SMA-4.1 | X | - | - | X | - | X | X | - | X | - | - | - | - | - | X | X | | | | 204C00245 | No | - | | |
| Water/Cañon de Valle | W-SMA-5 | X | - | X | - | - | X | X | - | X | - | X | - | Replace 1 rock check dam | 3K | - | | | | | - | - | - | | |
| Water/Cañon de Valle | W-SMA-6 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | X | X | | | | 201F04061 | No | - | | |
| Water/Cañon de Valle | W-SMA-7 | X | - | X | X | - | X | X | - | X | - | X | - | Remove wood debris from rock check dams | 3K | X | | | | | 200D02385 | | | | |
| Water/Cañon de Valle | W-SMA-7.8 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | X | | | | | 204B00773 | | | | |
| Water/Cañon de Valle | W-SMA-7.9 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | X | X | | | | 202E02313 | No | - | | |
| Water/Cañon de Valle | W-SMA-8 | X | - | X | - | - | X | X | - | - | X | - | X | Berm breach | 8K | X | X | | | | 210F01642 | No | - | Turned off after collection. | |
| Water/Cañon de Valle | W-SMA-8.7 | X | - | - | - | X | X | X | - | X | - | - | - | - | - | X | X | | | | 207F01613 | No | Yes | Sampler turned off after collection and battery removed from field. Reactivated 9/30/13. | |
| Water/Cañon de Valle | W-SMA-8.71 | X | - | X | - | - | X | - | X | X | - | - | - | - | - | X | x | - | - | - | 198C00804 | no | - | Turned off after collection. | |
| Water/Cañon de Valle | W-SMA-9.05 | X | - | X | - | - | X | X | - | - | X | X | - | Erosion on backside of 1 berm | 5K | X | X | | | | 204M00419 | No | - | Turned off after collection. | |
| Water/Cañon de Valle | W-SMA-9.5 | X | - | - | X | - | X | X | - | X | - | - | - | - | - | X | x | | | | 209F00289 | no | - | Sample missed; no liquid detected. | |
| Water/Cañon de Valle | W-SMA-9.7 | X | - | X | - | - | X | X | - | X | - | X | - | Replace 1 wattle | 2K | X | x | | | | 209F01143 | no | - | Turned off after sample collection. | |
| Water/Cañon de Valle | W-SMA-9.8 | X | - | X | - | - | X | X | - | X | - | - | - | - | - | X | x | | | | 209F00287 | no | - | | |
| Water/Cañon de Valle | W-SMA-9.9 | X | - | X | - | - | X | - | X | - | X | X | - | 1 berm breach | 5K | X | x | | | | 204C00268 | no | - | Turned off after sample collection. | |