

Structure	Location		Access				Structure Status							
	Watershed	Mesa Top	Canyon	Pavement	Dirt	Foot	Accessible	Watershed Control	Good Condition	Damaged	Routine Maintenance	Major Repair	MSS/TPMC	Cost: Minor-Green 0-5K, Moderate-Yellow 5-20K, Mod/Severe-Orange 20-50K, Severe-Red 50+K
Mortandad Canyon Sediment Traps	-	X	-	-	X	X - park at well pad, 0.5 mile walk (until dirt road repaired)	X	-	X	-	X	MSS	100K	Spillway reconstruction required. Sediment removal required. Pond modification required. Channel repair recommended. Install rolling berms on access road at confluence of Ten-Site and Mortandad Canyons. Hazard trees near E202 need to be removed.
Los Alamos Canyon Ponds	-	X	X	-	-	X	X	-	X	-	X	MSS	50K	Lower pond abutment, abutment face, and spillway require reconstruction.
DP Canyon Grade Control Structure	-	X	-	X	-	X - road repair required	X	X	-	X	-	MSS	5K	Road repair required.
Los Alamos Canyon Weir	-	X	X	-	-	X	X	X	-	X	-	MSS	150K	Woody debris and sediment removal required for all ponds.
Pueblo Canyon Grade Control Structure	-	X	X	-	-	X	X	X	-	X	-	MSS	50K	Woody debris removal required. Downstream erosion repairs include rip rap application.