

Monitoring Group	Watershed	Location	Damage Assessment	Remedial Actions	Waste Comments
TA-21	Los Alamos	LADP-3	No damage/impact.	None.	No Issues
TA-21	Los Alamos	LAOI(a)-1.1	Debris and sediment accumulation.	Clear pad of debris and sediment.	Any trash would be managed as GIC
TA-21	Los Alamos	LAOI-3.2	No damage/impact.	None.	NO Issues
TA-21	Los Alamos	LAOI-3.2a	No damage/impact.	None.	NO Issues
TA-21	Los Alamos	LAOI-7	No damage/impact.	None.	NO Issues
TA-21	Los Alamos	R-5	No damage/impact.	None.	No Issues
TA-21	Los Alamos	R-6	No damage/impact.	None.	No Issues
TA-21	Los Alamos	R-64	No damage/impact.	None.	No Issues
TA-21	Los Alamos	R-66	No damage/impact.	None.	No Issues
TA-21	Los Alamos	R-6i	No damage/impact.	None.	No Issues
TA-21	Los Alamos	R-8	No damage/impact.	None.	No Issues
TA-21	Los Alamos	R-9	Debris and sediment accumulation.	Clear pad of debris and sediment.	Any trash would be managed as LLW
TA-21	Los Alamos	R-9i	Debris and sediment accumulation.	Clear pad of debris and sediment.	Any trash would be managed as LLW
TA-21	Los Alamos	TA-53i	No damage/impact.	None.	No Issues
Chromium Investigation	Mortandad	MCOI-5	No damage/impact.	None.	No Issues
Chromium Investigation	Mortandad	MCOI-6	Debris and sediment accumulation.	Clear pad of debris and sediment.	Any trash would be managed as LLW
Chromium Investigation	Mortandad	R-1	Debris and sediment accumulation - minimal.	Clear pad of debris and sediment.	Any trash would be managed as Municipal waste
Chromium Investigation	Mortandad	R-13	No damage/impact.	None.	No Issues
Chromium Investigation	Mortandad	R-15	No damage/impact.	None.	No Issues
Chromium Investigation	Mortandad	R-28	Active operations underway - cleanup completed.	None.	No Issues
Chromium Investigation	Mortandad	R-42	Active operations underway - cleanup completed.	None.	No Issues
Chromium Investigation	Mortandad	R-44	No damage/impact.	None.	No Issues
Chromium Investigation	Mortandad	R-45	No damage/impact.	None.	No Issues
Chromium Investigation	Mortandad	R-50	No damage/impact. (mesa top location)	None.	No Issues
Chromium Investigation	Mortandad	R-61	No damage/impact. (mesa top location)	None.	No Issues
Chromium Investigation	Mortandad	R-62	No damage/impact. (mesa top location)	None.	No Issues
Chromium Investigation	Sandia	R-11	Debris and sediment accumulation.	Clear pad of debris and sediment.	Any trash would be managed as Municipal waste
Chromium Investigation	Sandia	R-35a	No damage/impact.	None.	No Issues
Chromium Investigation	Sandia	R-35b	No damage/impact.	None.	No Issues
Chromium Investigation	Sandia	R-36	No damage/impact.	None.	No Issues
Chromium Investigation	Sandia	R-43	No damage/impact.	None.	No Issues
Chromium Investigation	Sandia	SCI-1	No damage/impact.	None.	No Issues
Chromium Investigation	Sandia	SCI-2	No damage/impact.	None.	No Issues
MDA C	Mortandad	R-14	No damage/impact.	None.	No Issues
MDA C	Mortandad	R-46	No damage/impact. (active construction site).	None.	No Issues
MDA C	Mortandad	R-60	No damage/impact.	None.	No Issues
TA-54	Mortandad	R-21	No damage/impact.	None.	No Issues
TA-54	Mortandad	R-37	No damage/impact.	None.	No Issues
TA-54	Mortandad	R-38	No damage/impact.	None.	No issues
TA-54	Mortandad	R-55	No damage/impact.	None.	No Issues
TA-54	Mortandad	R-55i	No damage/impact.	None.	No Issues
TA-54	Pajarito	R-20	No damage/impact.	None.	No Issues

Monitoring Group	Watershed	Location	Damage Assessment	Remedial Actions	Waste Comments
TA-54	Pajarito	R-23	No damage/impact.	None.	No Issues
TA-54	Pajarito	R-23i	No damage/impact.	None.	No Issues
TA-54	Pajarito	R-32	No damage/impact.	None.	No Issues
TA-54	Pajarito	R-39	No damage/impact.	None.	No Issues
TA-54	Pajarito	R-40	No damage/impact.	None.	No Issues
TA-54	Pajarito	R-41	No damage/impact.	None.	No Issues
TA-54	Pajarito	R-49	No damage/impact.	None.	No Issues
TA-54	Pajarito	R-51	No damage/impact.	None.	No Issues
TA-54	Pajarito	R-52	No damage/impact.	None.	No Issues
TA-54	Pajarito	R-53	No damage/impact.	None.	No Issues
TA-54	Pajarito	R-54	No damage/impact.	None.	No Issues
TA-54	Pajarito	R-56	No damage/impact.	None.	No Issues
TA-54	Pajarito	R-57	No damage/impact.	None.	No Issues
TA-16-260	Pajarito	R-18	No damage/impact.	None.	No Issues
TA-16-260	Water	16-25280	Minor debris accumulation.	Clear pad of debris.	No Issues
TA-16-260	Water	16-26644	No damage/impact.	None.	No Issues
TA-16-260	Water	CdV-16-02656	No damage/impact;	None.	No Issues
TA-16-260	Water	CdV-16-02659	No damage/impact;	None.	No Issues
TA-16-260	Water	CdV-16-1(i)	Minor damage to pad from surface water runoff.	Regrade/place base course.	No Issues
TA-16-260	Water	CdV-16-2(i)r	No damage/impact.	None.	No Issues
TA-16-260	Water	CdV-16-4ip	No damage/impact.	None.	No Issues
TA-16-260	Water	CdV-16-611923	No damage/impact.	None.	No Issues
TA-16-260	Water	CdV-37-1(i)	No damage/impact.	None.	No Issues
TA-16-260	Water	CdV-R-15-3	No damage/impact.	None.	No Issues
TA-16-260	Water	CdV-R-37-2	No damage/impact.	None.	No Issues
TA-16-260	Water	MSC-16-06295	Debris accumulation.	Clear pad of debris.	No Issues
TA-16-260	Water	R-25b	No damage/impact.	None.	No Issues
TA-16-260	Water	R-26 PZ-2	No damage/impact.	None.	No Issues
TA-16-260	Water	R-26	No damage/impact.	None.	No Issues
TA-16-260	Water	R-47i	No damage/impact.	None.	No Issues
TA-16-260	Water	R-48	No damage/impact.	None.	No Issues
TA-16-260	Water	R-63	Saturated ground conditions.	Pad reworked for R-63i work.	No Issues
MDA AB	Ancho	R-29	No damage/impact.	None.	No Issues
MDA AB	Ancho	R-30	No damage/impact.	None.	No Issues
MDA AB	Water	R-27	No damage/impact.	None.	No Issues
MDA AB	Water	R-27i	No damage/impact.	None.	No Issues
General Surveillance	Frijoles, Ancho, and Chaquehui	R-31	No damage/impact.	None.	No Issues
General Surveillance	Los Alamos	LAO-3a	No damage/impact.	None.	No Issues
General Surveillance	Mortandad	CDBO-6	No damage/impact.	None.	No Issues
General Surveillance	Mortandad	MCO-5	Debris and sediment accumulation.	Clear pad of debris and sediment.	Any trash would be managed as LLW
General Surveillance	Mortandad	MCO-7	Debris and sediment accumulation.	Clear pad of debris and sediment.	Any trash would be managed as LLW
General Surveillance	Mortandad	R-16	No damage/impact.	None.	No Issues

Monitoring Group	Watershed	Location	Damage Assessment	Remedial Actions	Waste Comments
General Surveillance	Mortandad	R-16r	No damage/impact.	None.	No Issues
General Surveillance	Mortandad	R-33	Debris accumulation on pad.	Clear pad of debris.	Debris removal
General Surveillance	Pajarito	03-B-13	No damage/impact.	None.	No Issues
General Surveillance	Pajarito	18-MW-18	No damage/impact.	None.	No Issues
General Surveillance	Pajarito	PCAO-8	No damage/impact. (same pad as R-49)	None.	No Issues
General Surveillance	Pajarito	PCI-2	(same pad as R-17) No damage/impact.	None.	No Issues
General Surveillance	Pajarito	R-17	No damage/impact.	None.	No Issues
General Surveillance	Pajarito	R-19	No damage/impact.	None.	No Issues
General Surveillance	Pueblo	APCO-1	Well completely removed by channel erosion. Fence damaged.	Replace well????	Significant waste Management would be needed to replace this well
General Surveillance	Pueblo	POI-4	Minor damage to pad from surface water runoff.	Replace base course.	No Issues
General Surveillance	Pueblo	R-2	No damage/impact.	None.	No Issues
General Surveillance	Pueblo	R-24	No damage/impact.	None.	No Issues
General Surveillance	Pueblo	R-3	No damage/impact.	None.	No Issues
General Surveillance	Pueblo	R-3i	No damage/impact.	None.	No Issues
General Surveillance	Pueblo	R-4	No damage/impact.	None.	No Issues
General Surveillance	Pueblo	TW-2Ar	No damage/impact.	None.	No Issues
General Surveillance	Sandia	R-10	No damage/impact.	None.	No Issues
General Surveillance	Sandia	R-10a	No damage/impact.	None.	No Issues
General Surveillance	Sandia	R-12	No damage/impact.	None.	No Issues
General Surveillance	Sandia	SCA-2	No damage/impact.	None.	No Issues
General Surveillance	Water	WCO-1r	Debris acumulation.	Clear debris.	No Issues